

Errata: Exhibit 11. Emergency Response - Event Chronology (“Timeline”) Narrative

To supplement Exhibit 11, Emergency Response - Event Chronology (“Timeline”) Narrative, of the Survival Factors Factual Report of the Investigation, the investigation identified that the activity times of the following two incidental activities of the event, as described in pages 123 and 124, respectively, of the document, were inadvertently inaccurately reported (i.e. the events actually occurred an hour later than reported), which, based upon updated information as affirmed by Dixie / Enterprise Products, is hereby corrected as follows¹.

<u>Time</u>	<u>Information</u>
	<u>Source(s)</u> <u>Activity Summary</u>
11:37~ 10:37~	DEP-AN A Dixie / Enterprise Products (locally contracted) field technician [ident: SB] manually closed Block Valve at MP 437.43
11:39~ 10:39~	DEP-AN A Dixie / Enterprise Products field technician [ident: JP] confirmed the Block Valve at MP 437.43 had been manually closed by another field technician [ident: SB].

-- End of Report --

Compiled by: // s // Date July 31, 2008
Richard M. Downs, Jr.
Mechanical Engineer (Crashworthiness)
Investigator / Survival Factors – Working Group Chairperson

Supervisory review: // s // Date August 1, 2008
Gerald D. Weeks, PhD.
Chief, Human Performance and Survival Factors Division
Office of Railroad, Pipeline, and Hazardous Materials Investigations

¹ refer to the Exhibit 11 [original] document for identification / explanations of column titles, and acronym nomenclature / abbreviations, as cited in this errata sheet.